

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 07/23/2016
Investigation No. NA

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Eric Leigh (on behalf of Dorothy Lewis)



Photograph #1

Date: 07/23/2016

Comments: Repaired side access door lock. The locking mechanism consists of a large sliding bolt lock that was welded to the door and secured with a lock guard plate.



Photograph #2

Date: 07/23/2016

Comments: Repaired side access door lock. The locking mechanism consists of a large sliding bolt lock that was welded to the door and secured with a lock guard plate.

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 07/23/2016
Investigation No. NA

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Eric Leigh (on behalf of Dorothy Lewis)



Photograph #3

Date: 07/23/2016

Comments: Black Oxide Room door welded shut. No access to this room now.



Photograph #4

Date: 07/23/2016

Comments: Black Oxide Room door welded shut (close-up). No access to this room now.

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 07/23/2016

Facility Name: Lane Plating

County: Dallas

Investigation No. NA

EPA ID No: TXD007336571; SWR No: 31215


Investigator: Eric Leigh (on behalf of Dorothy Lewis)



Photograph #5

Date: 07/23/2016

Comments: Repair of roll-down Rectifier Room door (inside view).



Photograph #6

Date: 07/23/2016

Comments: Left and right sides of roll-down Rectifier Room door (close-ups) after repair. Bolts and a steel rod were inserted into the inside track system of the door.

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 07/23/2016

Facility Name: Lane Plating

County: Dallas

Investigation No. NA

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Eric Leigh (on behalf of Dorothy Lewis)



Photograph #7

Date: 07/23/2016

Comments: Outside view of the roll-down door to the Rectifier Room after repairs. Dumpster remains outside of the door.



Photograph #8

Date: 07/23/2016

Comments: Inside view of the roll-down door to the Rectifier Room after repairs.

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 07/23/2016

Facility Name: Lane Plating

County: Dallas

Investigation No. NA

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Eric Leigh (on behalf of Dorothy Lewis)



Photograph #9

Date: 07/23/2016

Comments: Window was not repaired.



Photograph #10

Date: 07/23/2016

Comments: Laboratory door was not repaired. SWS determined it was not feasible to repair the door.